

List of reference signs

- 1 chamber
- 2 inlet
- 3 outlet
- 4 rolling rotor
- 5 space bellow the rotor
- 6 space above then rotor
- 7 additional channel
- 8 control valve
- 9 shaft
- 10 projection
- 11 nut
- 12 hollow vessel
- 13 entrance opening
- 14 spraying head
- 15 central opening
- 16 brush
- 17 water spray nozzles